

# Fire in the production hall

On 16th January, we had a fire in the area of the P4U laser. This now demands both of external specialists as well as from our team a lot of hard work, dedication and time.

At about 11.30 a.m. the fire alarm of our company in the acrylic cutting area sounded. The alarmed employees informed the fire brigade, which entered the smoke-filled hall with several breathing apparatus teams (5 vehicles and 33 men were on site). After a short time, the fire was extinguished.

Since then, the production hall has been cleaned, freed from fire residues, partially rebuilt and completely repainted. The complete burning out of the laser

(including cables and insulation) resulted in a chlorine gas smoke mixture. The worst thing about it is that it reacts with the humidity in the air within 48 hours and turns into hydrochloric acid. Within a few days, this destroys all electrical components and causes metallic surfaces to rust.



Review of the day of the fire in the production hall.



## Facts and Figures

**Fire time:**  
16th January, 11.34 a.m.

**Value of the damage:**  
750.000 Euro

**Destroyed machines:**  
CNC laser cutting  
and engraving machine

**Duration until fire was out:**  
15 Minutes



18

19


20



**JANUARY 21** The employees of the Belfor company during special cleaning



**JANUARY 22** The changing production hall



The soot is combated as best as possible by the Belfor specialists. Every single machine and every part is carefully cleaned to prevent rusting.



**JANUARY 21**

**JANUARY 22**

**JANUARY 25**

**JANUARY 25** Back to the origin



The production staff help with the cleaning, repair and restoration work as best as they can. A team that sticks together!

Dare to be different

**JANUARY 25**



FEBRUARY  
**2**

## The new walls are in place



Dare to be different


▲ The new laser will not arrive until mid-April, but the special fire protection room for it is already ready.

FEBRUARY  
**2**

3

FEBRUARY  
**5**

## The hall slowly shines in new splendour



▲ Many walls are already freshly painted, and machines cleanly plastered.



Production is almost back in full swing and every employee is working diligently to ensure that spectacle wearers can wear their beloved Johann von Goisern as soon as possible.

The best way to overcome obstacles is with a team like that of the company POMBERGER Goisern. For this team, there are no problems, only solutions.

FEBRUARY  
**5**

6